Table 3 Coordinate system (KR for Steel Ships, Part 3, Annex 3-2, Page 139)

Axis	Direction	Positive orientation
X	Longitudinal	Forward (toward the bow)
Y	Transverse	Port (toward the left)
Z	Vertical	Deck (upwards)